


Queen City Substation

Vandalism and Theft



- On 9/21/22, a cut was observed in the east side of the substation fence, approximately 2-3 feet from the ground up.
- Fence detection cable was not cut.
- No alarms were received in this area of the fence for more than one month.
- Security observed/reported no unusual activity or suspicious activity just prior to this discovery.
- Security systems were working properly.
- No obvious theft or additional damage was noted at this time.





- Alarm history reviewed.
- Several alarms noted on 8/13/22 beginning at 0304 hours approximately.
- Alarms were acknowledged and area evaluated by on duty Security Officer who noted the site was secure and the reason for the alarm was unknown.
- No video was available due to “first in, first out” recording and duration of time that passed
- No evidence to support subject(s) entered the yard.
- No report to law enforcement at this time.

- During the 10/3/22 substation inspection, approximately 20 feet of copper grounds were observed cut/missing from the LA stand and the 33-1 and 33-2 switching structure.
- No additional vandalism/entry points were located in the fence.
- (Assumption that:) The theft occurred at approximately the same time as the fence alarms on 8/13/22.
- Damage repaired
- Notifications made;
 - Law enforcement
 - VT Department of Public Service
 - ISO-NE
 - GMP and BED

