

## TABLE OF CONTENTS

<b>1</b>	<b>INTRODUCTION AND BACKGROUND INFORMATION .....</b>	<b>1</b>
1.1	STUDY OBJECTIVE .....	1
1.2	ANALYSIS DESCRIPTION .....	2
1.3	STUDY ASSUMPTIONS .....	2
1.3.1	LOAD .....	2
1.3.2	NETWORK TOPOLOGY .....	8
1.3.3	GENERATION AND INTERFACE TRANSFERS .....	9
1.4	ANALYSIS METHODOLOGY .....	15
1.4.1	PLANNING STANDARDS AND CRITERIA .....	15
1.4.2	PERFORMANCE CRITERIA .....	15
1.4.3	CONTINGENCIES TESTED .....	19
<b>2</b>	<b>RESULTS OF TRANSMISSION ANALYSIS .....</b>	<b>1</b>
2.1	TPL-001 – CATEGORY A, NO CONTINGENCIES .....	23
2.2	TPL-002 – CATEGORY B, LOSS OF SINGLE ELEMENTS .....	23
2.3	TPL-003 – CATEGORY C, LOSS OF TWO OR MORE ELEMENTS .....	23
2.3.1	SINGLE EVENTS TRIPPING TWO OR MORE ELEMENTS WITH ALL LINES IN .....	23
2.3.2	SINGLE EVENTS TRIPPING ONE ELEMENT WITH A FACILITY OUT OF SERVICE .....	24
2.3.3	PERFORMANCE CRITERIA COMPLIANCE .....	29
2.3.4	INTERACTIONS WITH THE SUB-TRANSMISSION SYSTEM .....	31
2.3.5	RESULTS WITH THE VERMONT YANKEE GENERATOR UNAVAILABLE .....	33
2.4	TIMING OF TRANSMISSION DEFICIENCIES .....	36
2.4.1	RECOMMENDATIONS .....	38
2.4.2	EFFECTS OF THE PHASE SHIFTERS .....	38
2.4.3	EFFECTS OF MOVING THE NEWPORT BLOCK LOAD INTO VERMONT .....	40
2.5	TESTING WITH THE 2018 PROPOSED UPGRADES MODELED .....	41
2.5.1	RESULTS WITH HIGHGATE DECOMMISSIONED .....	41
2.5.2	2023 RESULTS .....	45
2.5.3	2028 RESULTS .....	46
<b>3</b>	<b>RESULTS OF SUB-TRANSMISSION ANALYSIS .....</b>	<b>51</b>
3.1	All-lines-in performance .....	51
3.1.1	VOLTAGE .....	51
3.1.2	THERMAL .....	51
3.2	TRANSMISSION CONTINGENCY PERFORMANCE .....	52
3.2.1	N-1 PERFORMANCE .....	52
3.2.2	N-1-1 PERFORMANCE .....	52
3.3	STEP-DOWN TRANSFORMER CONTINGENCY PERFORMANCE .....	55
3.3.1	RECOMMENDATIONS .....	60
3.4	SUB-TRANSMISSION CONTINGENCY PERFORMANCE .....	61
3.4.1	RECOMMENDATIONS .....	64
<b>4</b>	<b>CONCLUSIONS AND RECOMMENDATIONS .....</b>	<b>64</b>
<b>5</b>	<b>NTA SCREENING OF PROPOSED SOLUTIONS .....</b>	<b>78</b>
	<b>APPENDIX A – VSPC COMMENTS .....</b>	<b>87</b>
	<b>APPENDIX B – PUBLIC COMMENTS .....</b>	<b>88</b>
	<b>APPENDIX C – LOAD FORECAST .....</b>	<b>89</b>
	<b>APPENDIX D – CONTINGENCY LIST .....</b>	<b>91</b>
	<b>APPENDIX E – TABLES OF RESULTS .....</b>	<b>98</b>
	EAST-West Results – no phase angle regulator adjustments .....	99
	West-East Results – no phase angle regulator adjustments .....	117
	West-East Results – with 2018 upgrades modeled .....	137
	West-East Results – with Highgate decommissioned .....	144
	West-East Sub-transmission Results .....	152
	<b>APPENDIX F – CASE SUMMARIES .....</b>	<b>166</b>

**LIST OF FIGURES**

Figure 1: Vermont Load Zones..... 4  
Figure 2: Vermont Load Forecasts ..... 7

**LIST OF TABLES**

Table 1: Historical load ratio shares of the load zones ..... 6

Table 2: List of cases tested..... 12

Table 3: Base case dispatch and interface flow summaries ..... 13

Table 4: Base case dispatch and interface flow summaries with VY OUT ..... 14

Table 5: NERC performance criteria ..... 16

Table 6: Thermal and voltage criteria ..... 18

Table 7: West-East Thermal results..... 21

Table 8: West-East Voltage results..... 22

Table 9: Effects of VY-OUT on voltage support..... 34

Table 10: Effects of VY-OUT on West-East Thermal results ..... 35

Table 11: Effects of VY-OUT on East-West Thermal results ..... 35

Table 12: Load levels (MW load and losses) in timing analysis ..... 36

Table 13: Phase Shifter settings in limiting cases..... 39

Table 14: Effects of Highgate Decommissioned on Line Overloads..... 42

Table 15: Effects of Highgate Decommissioned on Transformer Overloads ..... 42

Table 16: Effects of Highgate Decommissioned on Line Overloads..... 44

Table 17: Effects of Highgate Decommissioned on Transformer Overloads ..... 44

Table 18: Summary of 2028 results..... 49

Table 19: Sub-transmission pre-contingency voltage violations ..... 51

Table 20: Sub-transmission pre-contingency thermal violations..... 51

Table 21: Transformer contingency results – Sub-transmission voltage violations ..... 58

Table 22: Transformer contingency results – Sub-transmission thermal violations ..... 59

Table 23: Sub-transmission contingency thermal violations ..... 61

Table 24: Sub-transmission contingency voltage violations..... 62

Table C-1: VELCO load forecast ..... 90

Table D-1: Transmission contingency list ..... 92

Table D-2: Sub-transmission contingency list ..... 96

Table E-1: East - West thermal results ..... 100

Table E-2: East - West thermal results with VY OUT ..... 106

Table E-3: East – West voltage results with alternate dispatches ..... 111

Table E-4: East – West voltage results with limiting facilities out..... 114

Table E-5: West – East thermal results..... 118

Table E-6: West – East thermal results with VY OUT ..... 125

Table E-7: West – East voltage results with alternate dispatches ..... 131

Table E-8: West – East voltage results with limiting facilities out..... 134

Table E-9: West – East thermal results with upgrades modeled..... 138

Table E-10: West – East voltage results with upgrades modeled ..... 141

Table E-11: West - East thermal results with Highgate Decommissioned ..... 145

Table E-12: West - East thermal results with Highgate Decommissioned and PV-20 230 kV upgrade..... 150

Table E-13: Sub-transmission thermal violations due to transmission contingencies ..... 153

Table E-14: Sub-transmission voltage violations due to transmission contingencies..... 158

Table E-15: Sub-transmission thermal violations due to sub-transmission contingencies ..... 161

Table E-16: Sub-transmission post-contingency voltage violations due to sub-transmission contingencies ..... 164