



vermont electric power company



VELCO Animal Mitigation

Operating Committee

June 21, 2018

VELCO Animal Mitigation Summary

- **Essex X10 – 34.5KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **Essex X20 – 34.5KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **Tafts Corner – 12.47KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket purchased requires portable transformer to install*
- **Tafts Corner – 34.5KV**
 - Squirrel – Transgard Fence installed,
 - *Bird – Gray Jacket Installed*
- **Limekiln – 34.5KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **Queen City – 13.8KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **Queen City – 34.5KV**
 - Squirrel – Transgard Fence installed,
 - *Bird – Gray Jacket Installed*
- **East Ave – 13.8KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **East Ave – 34.5KV**
 - Squirrel – Transgard Fence installed
 - *Bird – Gray Jacket Installed*
- **North Ferrisburg – 12.5KV**
 - Squirrel – Transgard Fence installed
- **Shelburne – 12.5KV**
 - Squirrel – Transgard Fence installed
- **Charlotte – 12.5KV**
 - Squirrel – Transgard Fence installed

Questions ?